



Most of Section TC06 had steep sideslope and just tons of rocks to pull out.



Many rocks and very fine soil. But the crew starts to make tread appear.



Before: not too steep here but plenty of rocks to remove.



After: the sun burned through the overcast just as this section was completed.



Who put the line right through this stump? Luckily we have a number of certified stump pullers.



If there wasn't a rockpile to work through, there was plenty of thick duff and deadfall to remove.



Final finish work on a new trail section. Some deadfall had to be cut off the trail here.



This tree was blocking line of sight down the trail. Dig out or cut? Getting tired, we'll just cut it for now.



On the section completed earlier, the crew worked to cut back the very steep backslope.



We're talking VERY steep backslope to cut back on this section.



Quite a bit of effort was expended on the backslope and tread leveling.



Before: blast through this cactus and Section TC06 will connect to Section TC05.



First a stump had to be popped out of the tread. We had just the right guy for that.



And the tread had to be cut in. It is very satisfying completing a long section.



Connection completed. Next session the crew will work on up towards Faulty Trail.



Headed for the barn: beautiful day on the mountain and it looks like the monsoon is finally firing up.