



Part of the crew cuts in the upper end of a short reroute to bypass an eroding climbing turn.



After: The upper end of the reroute is complete and the bypassed section obliterated.



The boss makes final adjustments to the new bermed turn.



The nice sustainable bermed turn is complete.



That's no baseball! Recent rains have the mushrooms popping out.



Before: Erosion in the steep turn on the right justified the reroute.



After: the steep section is obliterated, replaced by a more sustainable turn.



On the next reroute, the project lead had not cleared the corridor so everyone had to pitch in.



As the corridor opened up, the crew could start cutting tread. At least we were in the shade.



After lunch, obliteration began on the badly eroded user trail bypassed by the Madera Locura reroute.



There were plenty of bottlebrush trees on the climb to fill the old trail.



Teaming was effective on the larger debris. It got pretty hot up on the ridge.



The masticated area had plenty of debris to pull in as the crew worked their way down.



A slimleaf purple mustard competes with young oak.