



At Ranger Rock, a new retaining wall was completed to back up the future informational kiosk.



Another team rerouted and better defined the upper trail to the climbing location.



New tread and thinning slash serve to define the upper trail and guide trail users.



The cleaned up tread winds up to the top of the outcrop.



Another team completed some very nice steps to improve access to the belay platforms.



A crib and fill project improved this belay platform.



The top of the outcrop was completely swept clean of all the loose rolling rubble.



Project completed and climbers have already started bringing their gear up to play.