




Saddle up! The crew is looking forward to the change in conditions and scenery at 10k North.



The crew progressed along the reroute, alternating between deep shade and bright sunshine.



Much of the work involved sections of tread leveling, refining backslope, and removing forest debris.



Finishing touches on this climb complete the task.



The boss wanted the tread a little wider around this tree.



Whoa! Another new one for the crew: cutleaf groundsel amid the rotting deadfall.



The crew keeps moving along the reroute, completing finish work identified by the trail boss.



Decisions, decisions: this rock is loose but is it worth removing?




Cribbing work begins on a steep section studded with big limestone outcrops.



After lunch, additional horsepower was applied so the crew could complete the cribbed section.




Boom! Finished tread on the cribbed section: the FOSM trail crew just loves this stuff.



Cutting the backslope and widening the tread around a tree.



The velvet umbrellawort is in full bloom in the meadows.



Back at the 10k North trailhead. The trail day was just perfect!